



## ***Problems with Ultrasound Probes: Do Not Despair – Get It Repaired***



Like many pieces of equipment, ultrasound transducers and TEE probes will have issues arise over their lifespan. However, a transducer not working properly does not automatically mean that it needs replacement or a repair / exchange.

Life Systems, Inc. can now offer high-quality transducer repairs at the fraction of the cost of replacing the probes. Hospitals and health organizations are already budget-strapped. Save department funds for critical items and repair your ultrasound and TEE probes.

Many times a probe is replaced because the OEM indicates that repair is not an option. A new transducer will typically cost \$8,000 to \$20,000, or more, depending on the type of probe and manufacturer.

There are many instances where the probe can be repaired for significantly less than a new unit. Why not let Life Systems do it for you?

Similar to our endoscopy repairs, all ultrasound probe repairs meet manufacturer specifications before they are returned to the customer. All repair work performed on your ultrasound transducers is guaranteed for 90 days.

There is no charge to have Life Systems evaluate your ultrasound transducers for repair. Customers may send damaged probes to us and we will send a free repair estimate without any obligation – you decide.

### **Specializing in Repair of Major Brands**

- Acuson, ATL, Agilent/Hewlett-Packard, GE, Philips, Siemens and Medison and more.


### **Typical Repairs on Standard Transducers**

- Transducer lens (array) replacement
- Strain relief recasting
- Cable jacket repair
- Cable replacement
- Probe casing repair or replacement
- Connector repair or replacement
- Full cosmetic refurbishment

### **Typical Repairs on TEE Probes**

- Bending neck rubbers
- Insertion tube recoating or replacement
- Angulation cable replacement
- Angulation mechanism repair
- Lens replacement
- Connector repair
- Cable jacket repair

LSI-TRANS-0207



## **Life Systems, Inc.**

515 Trade Center Boulevard  
Chesterfield, MO 63005  
Phone: 636.787.2100  
Fax: 636.787.0016

Toll free: 888.LIFE.SYS / 888.543.3797  
[www.lifesystemsinc.com](http://www.lifesystemsinc.com)